## DATOS DEL PID DE LA MAQUINA 1806

	PID DEL EXTRUSOR ESPUMA							
	P GAIN	I 1/SEC	D SEC	COOL %	PROC LO	PROC HI	DEV ALARM	
ZONA 2	8	0.052	0	1	0	300	5	
ZONA 3	6.9	0.013	0.5	2	0	300	5	
ZONA 4	2.2	0.008	0	2	0	300	5	
ZONA 5	4.2	0.001	0.5	2	0	300	5	
ZONA 6	3.8	0.014	0.5	2	0	300	5	

	PID DEL EXTRUSOR SOLIDO							
	P GAIN	I 1/SEG	D SEG	COOL %	PROC LO	PROC HI	DEV ALARM	
ZONA 1	0	0	0	1.2	0	300	5	
ZONA 2	0	0	0	1	0	300	5	
ZONA 3	0	0	0	1	0	300	5	

	PID DE TEMPERATURA DE DADOS							
	P GAIN	I 1/SEC	D SEC	COOL %	PROC LO	PROC HI	DEV ALARM	
MORDAZA HORIZONTAL	9	0.05	0	1	0	300	5	
BRIDA HORIZONTAL	8	0.001	0	1	0	300	5	
CABEZAL	9	0.001	0	1	0	300	5	
DADO	9	0.001	0	1	0	300	5	
BRIDA VERTICAL	8	0.001	0	1	0	300	5	
CUELLO VERTICAL	8	0.001	0	1	0	300	5	

**NOTA**: El SETPOINT son las temperaturas del extrusor espuma, solido y temperaturas de dados y depende del proceso que ustedes manejen. **Estos setpoints se encuentran en las hojas de proceso que tiene el operador.**